

# OM-120

## Firmware Revision Notes

Version 1.2.1

# Firmware Version 1.2.1 (Build No.1.2.1\_220103)

Release: 2022-01-05

1. New Features and Improvements
  - 1.1. Improvements related to RS-485 communication.
2. Bug Fixes
  - 2.1. The door relay did not operate according to the input status due to a relay 6-11 port order error (Affects version: v1.0.0).

# Firmware Version 1.2.0 (Build No.1.2.0\_200624)

Release: 2020-07-09

1. New Features and Improvements
  - 1.1. Added feature to change device ID.
2. Bug Fixes
  - 2.1. Mac error occurs when RS-485 communication does not comply with OSDP standard.

# Firmware Version 1.1.0 (Build No.1.1.0\_181031)

Release: 2018-11-26

1. New features and improvements
  - 2.2. If the data transmission fails when communicating with OSDP, it is transmitted again.
  - 2.3. The OSDP ID command does not respond if a user changes the OSDP key using Secure I/O 2.

# Firmware Version 1.0.0 (Build No.1.0.0\_170103)

Release: 2017-01-03

1. Initial firmware developed.



Suprema Inc.  
16F Parkview Tower  
248, Jeongjail-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, 463-863 Republic of Korea  
Tel.+82-31-783-4502 Fax.+82-31-783-4503  
sales@supremainc.com www.supremainc.com